

विभाग/क्षेत्र कोलियरी Dept/Area/Colliery.....

जावक क्रमांक :-वेकोलि/वक्षे/उक्षेप्र/घुउक्षे/सिविल/22-23/

669

दि :16/03/2023

## **BUILDING STRUCTURE / SAFETY CERTIFICATE**

This is to certify that D.A.V. Public School at Neeljay Township, Sunder Nagar, Tq. Wani, Dist. Yavatmal{MS} comprise of basements and upper floors are constructed on the basis of Guidelines issued by the Central Board of Secondary Education, Delhi particularly in dimensions / structure of Class Rooms, Laboratories, Activity Rooms, Library, Museum & Conference Hall etc. for running the school from Class LKG to Std. XII.

The dimensions of Classrooms, Laboratories, Activity Rooms, Library, Museum, Conference Hall, Other Rooms, Staircase with handle, separate urinals & toilet seats for boys, girls ladies & gents staff is strictly followed as per the CBSE Norms.

The school building is constructed with RCC pillars with slab and the structure of the building is designed in such manner that the each and every corner of the school is easily accessible to the students, staff & parents including person with disability. In case of any kind of emergency the building is provided with three separate exits in different directions of the building with Security Guards. The building provided with lighting conductor for safety from lightning.

The school is provided with all physical facilities for security like permanent compound wall with separate entrance & exits, playground, furniture & fixtures, electricity, tap water facility & ramp of person with disability and safe in all respect for children & is approved by WCL authorities Govt. of India U/t.

It is noteworthy to mention that, as the minning site of the Western coal fields Ltd is nearing the school land after a period of 26 years DAV Public School, Neeljay Wani Area has undergone Building stability Audit by the Committee of Deptt. of Civil Engineering Vishveshwaraya National Institute of Technology Nagpur. As per this stability report on Dtd. 07/02/2023 back part of the building 15 Rooms of the 72 rooms have been evacuated for the safety of children. As per recommendation of the stability report committee recommendation the further safety norms are being followed and inspection committee reassures safety in every 3 months. The process for administrative and financial approval forpurchase of land as per rules, change in site of school for reconstruction is in process and forwarded to the competent authority to be completed within the stipulated period as suggested by the Committee. (2-3 years)

Copy of the Building Audit Committee report attached

Sr. MANAGER (CIVIL)

NEELJAY SUB AREA

WCL, WANL AREA

(CIVIL)

Keeljai Sub-Area प्रभारी (निवृत्ति) नीलणई उपक्षेत्र